	7 (hy	Approved For Release 2003/08/11 100 RD 882-00457R006900500011-3	4 UV 368			
	CLASSIFICATION_SOZOT					
COUNTR	?Y	REPORT NO	_25X1			
		Panahiron A1 x P1 a 3 d Newscholder green and a commence and a commence of the				
e me respendencement	na santakan da ka					
25X1 EVALUAT	TION_	PLACE OBTAINED.	25X1			
		TENT 30 to 27 Penamber 1950				
		DATE PREPARED 30 Innuary 3057				
25X1 REFERE			enne, merranet de 1907a d			
		2 ENCLOSURES (No. & TYP!)				
REMARK	۸S		NACE AND DESCRIPTIONS OF THE PARTY OF THE PA			
Carrie South	t in consequent color of		NOON PURSON TO AN ADVISOR OF THE			
25X1	маска житак.		CALL ROOM PROPERTY ATTE			
		·				
25X1 25X1 25X1	2.	Building naterials and equipment were continually being shipped by rail to the Merseburg (M 52/D 91) airfield. Brick clinker, cement, boards, beams, field railway equipment, and conveyor belts were observed primarily. On 10 December 1950, 136 lowries, three Diesel engines, five conveyor belts and an excavator were seen at the field. About 500 cubic meters of cement were also seen.	(1)			
25/1		Poles, strung with electric wires, were located throughout the entire landfield. Sunday and night shifts have worked regularly since 10 December 1950. The construction is said to be scheduled for completion in May 1951. (5)	ing			
25X1		Corments.				
		The arrival of building materials for the enlargement of the airfield was previously reported.	25X1			
	(2)	The stated boundaries of the enlarged landing field agree approximately with a sketch attached to a previous report.  It is believed that the projected runway will be extended to the west beyond the present boundary of the landing field.  According to a previous report, the field was also scheduled to be enlarged	25X1			
25X1		to the north.				
25X1						
		Document He. 10				
		CLASSIFICATION SECRET No Change in Class.	•			
25X1		CONFIDENTIAL  CO	25X1			

Approved For Release 2003/08/11 : CIA-RUP-82-00457R006900500011-3									
	•								
SHO	2				25X1				
1									

25X1

(4) It appears improbable that two parallel runways would be scheduled for construction. One of these two runways presumably is a concrete taxiway. Details on the courses of the runway and taxiway are not yet available.
(5) This date is reported for the first time.

